October 26, 2020 J5174-04-01

Worcester Public Schools 20 Irving Street Worcester, MA 01609, MA 02035

Attn.: Ms. Kristen Tran,

Environmental Health & Safety Coordinator

RE: PCB BMP Quarterly Status Report, 2020-2021 School Year

First Quarter, September 2020

Doherty High School

Dear Kristen,

In accordance with the Worcester Public School's (WPS) authorization, O'Reilly Talbot & Okun Associates, Inc. (OTO) is pleased to present this quarterly status report of the Best Management Practices (BMPs) implemented at the Doherty High School (Doherty). This status report represents the first quarter of the 2020-2021 school year. The objective of the BMP program is to reduce potential exposures to polychlorinated biphenyls (PCBs).

Certain materials used in the construction and renovation of buildings between 1950 and 1980 may contain PCBs. Doherty High School was constructed during this period. The US Environmental Protection Agency (USEPA) has recommended that a BMP program be implemented in schools and other buildings either constructed or renovated during this period.

WPS and its staff are responsible for implementing the BMPs at Doherty High School, and OTO responsible for conducting quarterly independent evaluations to provide WPS management with an assessment of the effectiveness of the BMPs implementation.

Best Management Practices (BMPs)

In its July 28, 2015 guidance for school administrators and other building owners and managers titled "Practical Actions for Reducing Exposure to PCBs in Schools and Other Buildings," the USEPA described potentially useful BMPs, including:

 Ensuring that ventilation systems are operating properly and are regularly inspected and maintained according to system manufacturer instructions and guidelines or ANSI/ASHRAE/ACCA Standard 180-2012—Standard Practice for Inspection and Maintenance of Commercial Building HVAC Systems. If system cleaning is needed, follow ANSI/ACCA Standard 6–Restoring the Cleanliness of HVAC Systems (2007);

- 2. Cleaning inside schools and other buildings frequently to reduce dust and residue;
- 3. Using a wet or damp cloth or mop to clean surfaces;
- 4. Using vacuum cleaners with high efficiency particulate air (HEPA) filters;
- 5. Not sweeping with dry brooms or using dry cloth wipes for dusting;
- 6. Washing hands with soap and water, particularly before eating; and
- 7. Washing children's toys.

We understand that WPS has modeled its BMP program for Doherty High School on EPA's guidelines. OTO's assessment of BMP effectiveness focuses on items 1 through 5 on this list. Regarding item 6, all school lavatories are equipped with soap and water and it is the responsibility of students and staff to maintain personal cleanliness. Item 7 on the list is not relevant to high school environments.

Assessment of BMPs at Doherty High School

We conducted the first quarter of the 2020-2021 school year BMP assessment at Doherty on September 24, 2020 accompanied by representatives from the District and School environmental and facilities department. The Heating, Ventilation, and Air-Conditioning (HVAC) system underwent a significant overhaul approximately 3 years ago and was operating properly at the time of the BMP assessment.

Because window and door caulking in the School may contain PCBs, WPS has previously applied a layer of non-PCB caulk over the previously existing caulking to reduce the potential for exposures. OTO observed twenty-nine (29) classrooms or other representative spaces in the school selected at random during the assessment. Our observations focused on the presence of dust on windows, window sills and window frames as well as the univent systems that provide heating and ventilation to the classrooms.

The school spaces we observed included:

- Administration and Guidance offices,
- Cafeteria.
- Library Media Center, and
- Selected classrooms.

Our general observations are summarized on Table 1 (attached). During the assessment we observed small amounts of missing caulk that we identified at the time to District and School facilities representatives.



Based on our discussions and observations, it is our conclusion that the implementation of the BMPs at Doherty is effective. The univents were generally free of significant dust and visible oil leakage. Except as noted above, most rooms exhibited only slight accumulation of dust.

Note that WPS has also authorized OTO to conduct annual indoor air monitoring for PCBs at Doherty. The full air testing reports are provided separately from the BMP reports, although we note that the air monitoring results have been well below USEPA guidelines for PCB concentrations in school air for each of the sampling rounds completed to date.

Other USEPA Recommendations for Suspected PCBs in Schools

Although not technically BMPs, USEPA made three other recommendations in its July 28, 2015 guidance for PCBs in schools:

- Remove all PCB containing fluorescent light ballasts (FLBs);
- Give consideration to encapsulating suspected PCB containing materials (such as caulk) to further reduce the potential for PCB exposure; and
- Removing suspect PCB containing building materials during planned renovations and repairs.

WPS removed all suspect PCB containing FLBs in 2012. There are no suspected PCB FLBs remaining in the Worcester school system.

In 2012 WPS also encapsulated the suspect PCB containing caulk around all of the windows and doors at Doherty with an additional thick layer of non-PCB caulk. Exterior suspect caulking was likewise covered with new caulk to a height of eight feet above grade. WPS subsequently over-caulked the remainder of the building's exterior door, window, and expansion joints in September and October 2018. This over-caulking is repaired as-needed to maintain its condition.

Finally, it is noted that WPS has applied to the state sponsored school building financing program for help with the replacement of the Doherty High School building. It is estimated that the current building will be replaced in approximately seven years. When Doherty is replaced, the suspect PCB containing materials will be removed and disposed of in accordance with applicable regulatory requirements.

Conclusions and Recommendations

In conclusion, it is our opinion that the BMPs are being implemented in an effective manner at Doherty High School. We recommend that the next quarterly on-site visit be conducted December of 2020.



Should you have questions or require additional information, please contact the undersigned.

Sincerely,

O'Reilly, Talbot & Okun Associates, Inc.

Christine Arruda, CIEC

Project Manager

James Okun, LSP

Robert Kirchherr, CS

Principal

Attachments Table 1 – Summary of Observations for Doherty High School

cc Mr. James Bedard,

Director of Environmental Management and Capital Projects

Table 1 - Summary of BMP Observations Doherty Memorial High School 299 Highland Street Worcester, MA 01602 September 24, 2020

Room	Condition of Caulk	Condition of Univents	Dust Accumulation	Comments
Adminitrative Office	VG	VG	VG	
Guidance Office	VG	VG	VG	
107	VG	VG	VG	
Cafeteria	VG	VG	VG	
200s Hall, end of hall windows	VG	VG	VG	
213	VG	VG	VG	
211	VG	VG	VG	
207	VG	VG	VG	
Library/Media center	VG	VG	VG	
204	VG	VG	VG	
Transition Hall A	VG	VG	VG	
316	VG	VG	VG	
322	VG	VG	VG	
326	VG	VG	VG	
Transition Hall B	VG	VG	VG	
334	VG	VG	VG	
400s Hall, end of hall windows by 425/430	VG	VG	VG	Left side, top pane, bottom seam, 12" caulk missing
430	VG	VG	М	
426	VG	VG	VG	
420	VG	VG	VG	
415	VG	VG	VG	
412	VG	VG	VG	
Stairwell to Upper Gym Hall	VG	VG	VG	Right bottom pane, bottom seam, 18" caulk missing. Left top pane, bottom seam, 18" caulk missing.
Upper Gym Hallway	VG	VG	VG	2nd window bank from left: top pane, right side, bottom seam, 3" caulk missing. 3rd long window bank from right, top pane, top seam, 3" caulk missing. 8th long window bank from right, top pane, bottom seam, 8" caulk missing.
301	VG	VG	VG	
310	VG	VG	VG	
314	VG	VG	VG	
104	VG	VG	VG	
101	VG	VG	VG	

CATEGORIZATION

Very good = minimal dust or debris Little = enough dust to leave a residue on a gloved finger Moderate = visible accumulations of dust Significant = thick layer of dust