



February 8, 2021
J5174-04-01

Worcester Public Schools
20 Irving Street
Worcester, MA 01609, MA 02035

Attn.: Ms. Kristen Tran,
Environmental Health & Safety Coordinator

RE: PCB BMP Quarterly Status Report, 2020-2021 School Year
Second Quarter, December 2020
Doherty High School

Dear Kristen,

In accordance with the Worcester Public School's (WPS) authorization, O'Reilly Talbot & Okun Associates, Inc. (OTO) is pleased to present this quarterly status report of the Best Management Practices (BMPs) implemented at the Doherty High School (Doherty). This status report represents the second quarter of the 2020-2021 school year. The objective of the BMP program is to reduce potential exposures to polychlorinated biphenyls (PCBs).

Certain materials used in the construction and renovation of buildings between 1950 and 1980 may contain PCBs. Doherty High School was constructed during this period. The US Environmental Protection Agency (USEPA) has recommended that a BMP program be implemented in schools and other buildings either constructed or renovated during this period.

WPS and its staff are responsible for implementing the BMPs at Doherty High School. OTO personnel are responsible for conducting quarterly independent evaluations to provide WPS management with an assessment of the effectiveness of the BMPs implementation.

Best Management Practices (BMPs)

In its July 28, 2015 guidance for school administrators and other building owners and managers titled "Practical Actions for Reducing Exposure to PCBs in Schools and Other Buildings," the USEPA described potentially useful BMPs, including:

1. Ensuring that ventilation systems are operating properly and are regularly inspected and maintained according to system manufacturer instructions and guidelines or ANSI/ASHRAE/ACCA Standard 180-2012—Standard Practice for Inspection and Maintenance of Commercial Building HVAC

Systems. If system cleaning is needed, follow ANSI/ACCA Standard 6—Restoring the Cleanliness of HVAC Systems (2007);

2. Cleaning inside schools and other buildings frequently to reduce dust and residue;
3. Using a wet or damp cloth or mop to clean surfaces;
4. Using vacuum cleaners with high efficiency particulate air (HEPA) filters;
5. Not sweeping with dry brooms or using dry cloth wipes for dusting;
6. Washing hands with soap and water, particularly before eating; and
7. Washing children's toys.

We understand that WPS has modeled its BMP program for Doherty High School on EPA's guidelines. OTO's assessment of BMP effectiveness focuses on items 1 through 5 on this list. Regarding item 6, all school lavatories are equipped with soap and water and it is the responsibility of students and staff to maintain personal cleanliness. Item 7 on the list is not relevant to high school environments.

Assessment of BMPs at Doherty High School

We conducted the second quarter of the 2020-2021 school year BMP assessment at Doherty on December 28, 2020 accompanied by representatives from the District and School environmental and facilities department. The Heating, Ventilation, and Air-Conditioning (HVAC) system underwent a significant overhaul approximately 3 years ago and was operating properly at the time of the BMP assessment.

Because window and door caulking in the School may contain PCBs, WPS has previously applied a layer of non-PCB caulk over the previously existing caulking to reduce the potential for exposures. OTO observed twenty-four (24) classrooms or other representative spaces in the school selected at random during the assessment. Our observations focused on the presence of dust on windows, windowsills and window frames as well as the univent systems that provide heating and ventilation to the classrooms.

The school spaces we observed included:

- Administration and Guidance offices,
- Cafeteria,
- Library Media Center,
- An Auto-shop classroom, and
- Other Selected classrooms.

Our general observations are summarized on Table 1 (attached). During the assessment we observed generally small sections (2" to 3"), along with a few larger seams (18" to 24",

specifically in rooms 214, 324, 328, and 419) of missing caulk that we identified at the time to District and School facilities representatives. In addition, although the majority of caulked areas observed were rated as “Very Good” (minimal dust or debris), the Cafeteria and Room 414 were identified to have “Little” to “Moderate” dust accumulation. These areas were also identified to District and School facilities representatives at the time of assessment.

Based on our discussions and observations, it is our conclusion that the implementation of the BMPs at Doherty is generally effective. The univents were generally free of significant dust and visible oil leakage.

Note that WPS has also authorized OTO to conduct annual indoor air monitoring for PCBs at Doherty. The full air testing reports are provided separately from the BMP reports, although we note that the air monitoring results have been well below USEPA guidelines for PCB concentrations in school air for each of the sampling rounds completed to date.

Other USEPA Recommendations for Suspected PCBs in Schools

Although not technically BMPs, USEPA made three other recommendations in its July 28, 2015 guidance for PCBs in schools:

- Remove all PCB containing fluorescent light ballasts (FLBs);
- Give consideration to encapsulating suspected PCB containing materials (such as caulk) to further reduce the potential for PCB exposure; and
- Removing suspect PCB containing building materials during planned renovations and repairs.

WPS removed all suspect PCB containing FLBs in 2012. There are no suspected PCB FLBs remaining in the Worcester school system.

In 2012 WPS also encapsulated the suspect PCB containing caulk around the windows and doors at Doherty with an additional thick layer of non-PCB caulk. Exterior suspect caulking was likewise covered with new caulk to a height of eight feet above grade. WPS subsequently over-caulked the remainder of the building’s exterior door, window, and expansion joints in September and October 2018. This over-caulking is repaired as needed to maintain its condition.

Finally, it is noted that WPS has applied to the state sponsored school building financing program for help with the replacement of the Doherty High School building. Currently, it is anticipated that the new Doherty High School building will open in 2024. Subsequent to the opening of the new School, the suspect PCB containing materials in the former Doherty High building will be removed and disposed of in accordance with applicable regulatory requirements.

Conclusions and Recommendations


In conclusion, it is our opinion that the BMPs are being implemented in an effective manner at Doherty High School. We recommend that the next quarterly on-site visit be conducted February of 2021.

Should you have questions or require additional information, please contact the undersigned.

Sincerely,
O'Reilly, Talbot & Okun Associates, Inc.



Christine Arruda, CIEC
Project Manager



James Okun, LSP
Principal



Robert Kirchherr, CSP
Principal

Attachments Table 1 – Summary of Observations for Doherty High School

cc Mr. James Bedard,
Facilities Director

Table 1 - Summary of BMP Observations
Doherty Memorial High School
299 Highland Street
Worcester, MA 01602
December 28, 2020

Room	Condition of Caulk	Condition of Univents	Dust Accumulation	Comments
105 Career Center	VG	VG	VG	---
106	VG	VG	VG	---
Cafeteria	VG	VG	L	---
208	VG	VG	VG	---
212	VG	VG	VG	---
214	VG	VG	VG	4th window from left, middle pane, left side, bottom seam, 18" caulk missing
330	VG	VG	VG	---
336	VG	VG	VG	2nd window from left, bottom pane, right side, top seam, 3" caulk missing
Library/Media center	VG	VG	VG	---
202	VG	VG	VG	---
318	VG	VG	VG	---
324	VG	VG	VG	Far right window, bottom pane, left side, 18" caulk missing. 4th window from left, middle pane, top right corner, 2" missing caulk. White board covering two windows from far right.
328	VG	VG	VG	Far right window, middle pane, entire bottom seam and 24" left seam caulk missing. 2nd window from right, middle pane, left side, 4" caulk missing
424	VG	VG	VG	---
421	VG	VG	VG	---
425	VG	VG	VG	Far right window blocked
419	VG	VG	VG	2nd window from left, bottom pane, top seam, entire seam missing caulk
414	VG	VG	M	---
407	VG	VG	VG	Middle window, middle pane blocked by wood
302A Woodshop	VG	VG	VG	---
306	VG	VG	VG	---
312	VG	VG	VG	3rd window from left, bottom pane, top seam entirely missing caulk
Stairwell 200 to 100	VG	VG	VG	Right of door, top pane, right side, bottom seam, 4" missing caulk
103	VG	VG	VG	---

CATEGORIZATION

Very good = minimal dust or debris

Little = enough dust to leave a residue on a gloved finger

Moderate = visible accumulations of dust