August 15, 2023 J5174-04-06

Worcester Public Schools 20 Irving Street Worcester, MA 01609

Attn.: Ms. Kristen Tran,

Environmental Health & Safety Coordinator

RE: PCB BMP Quarterly Status Report, 2022-2023 School Year

Fourth Quarter, June 2023 Burncoat High School

Dear Kristen,

In accordance with the Worcester Public School's (WPS) authorization, O'Reilly Talbot & Okun Associates, Inc. (OTO) is pleased to present this quarterly status report of the Best Management Practices (BMPs) implemented at the Burncoat High School (Burncoat). This status report represents the fourth quarter of the 2022-2023 school year. The objective of the BMP program is to reduce potential exposure to polychlorinated biphenyls (PCBs).

Certain materials used in the construction and renovation of buildings between 1950 and 1980 may contain PCBs. Burncoat High School was constructed during this period. The U.S. Environmental Protection Agency (USEPA) has recommended that a BMP program be implemented in schools and other buildings either constructed or renovated during this period.

WPS and its staff are responsible for implementing the BMPs at Burncoat High School. OTO personnel are responsible for conducting quarterly independent evaluations to provide WPS management with an assessment of the effectiveness of the BMPs implementation.

### **Best Management Practices (BMPs)**

In its July 28, 2015 guidance for school administrators and other building owners and managers titled "Practical Actions for Reducing Exposure to PCBs in Schools and Other Buildings" the USEPA described potentially useful BMPs, including:

 Ensuring that ventilation systems are operating properly and are regularly inspected and maintained according to system manufacturer instructions and guidelines or ANSI/ASHRAE/ACCA Standard 180-2012—Standard Practice for Inspection and Maintenance of Commercial Building HVAC Systems. If system cleaning is needed, follow ANSI/ACCA Standard 6–Restoring the Cleanliness of HVAC Systems (2007);

- 2. Cleaning inside schools and other buildings frequently to reduce dust and residue;
- 3. Using a wet or damp cloth or mop to clean surfaces;
- 4. Using vacuum cleaners with high efficiency particulate air (HEPA) filters;
- 5. Not sweeping with dry brooms or using dry cloth wipes for dusting;
- 6. Washing hands with soap and water, particularly before eating; and
- 7. Washing children's toys.

We understand that WPS has modeled its BMP program for Burncoat High School on EPA's guidelines. OTO's assessment of BMP effectiveness focuses on items 1 through 5 on this list. Regarding item 6, all school lavatories are equipped with soap and water, and it is the responsibility of students and staff to maintain personal cleanliness. Item 7 on the list is not relevant to high school environments.

## Assessment of BMPs at Burncoat High School

We conducted the fourth quarter, 2022-2023 school year BMP assessment at Burncoat on June 28, 2023, accompanied by representatives from the District and School environmental and facilities department. The Heating, Ventilation, and Air-Conditioning (HVAC) system was operating properly at the time of the BMP assessment.

Because window and door caulking in the school may contain PCBs, WPS has previously applied a layer of non-PCB caulk over the previously existing caulking to reduce the potential for exposures. OTO observed twenty-four (24) classrooms or other representative spaces in the school selected at random during the assessment. Our observations focused on the presence of dust on windows, windowsills, and window frames as well as the univent systems that provide heating and ventilation to the classrooms.

The school spaces we observed included:

- Cafeteria,
- Library / Media Center,
- Gymnasium hallway, and
- Other Selected classrooms or learning areas

Our general observations are summarized on Table 1 (attached). Univents were generally free of significant dust and visible oil leakage. Several rooms/areas observed had "little" (minimal dust or debris) to "moderate" (visible accumulations of dust) dust accumulation along the windowsills and univents. One room was observed with deteriorating or missing



PCB BMP Quarterly Examination Fourth Quarter, 2022-2023 School Year Burncoat High School August 15, 2023 J5174-04-06

non-PCB caulk. Windows with deteriorating or missing caulk and moderate dust accumulation were identified at the time to District and School facilities representatives and are documented in the attached Table.

Based on our discussions and observations, it is our conclusion that the implementation of the BMPs at Burncoat is generally effective. We recommend that areas observed with missing caulk receive an application of non-PCB caulk sealant, and that areas noted to have moderate dust accumulation be cleaned in accordance with "Practical Actions for Reducing Exposure to PCBs in Schools and Other Buildings" guidance.

WPS authorized OTO to conduct annual indoor air monitoring for PCBs at Burncoat High School. The full air testing reports are provided separately from the BMP reports. Air monitoring results have been below USEPA guidelines for PCB concentrations in school air for each of the sampling rounds completed to date.

### Other USEPA Recommendations for Suspected PCBs in Schools

Although not technically BMPs, USEPA made three other recommendations in its July 28, 2015 guidance for PCBs in schools:

- Remove all PCB containing fluorescent light ballasts (FLBs);
- Give consideration to encapsulating suspected PCB containing materials (such as caulk) to further reduce the potential for PCB exposure; and
- Removing suspect PCB containing building materials during planned renovations and repairs.

WPS removed all suspect PCB containing FLBs in 2012. There are no suspected PCB FLBs remaining in the Worcester school system.

In 2012 WPS encapsulated the suspect PCB containing caulk around the windows and doors at Burncoat with an additional layer of non-PCB caulk. Exterior suspect caulking was likewise covered with new caulk to a height of eight feet above grade. WPS subsequently over-caulked the remainder of the building's exterior door, window, and expansion joints in September and October 2018. This over-caulking is repaired as needed to maintain its condition.

Finally, WPS has applied to the State sponsored school building financing program for help with the replacement of the Burncoat High School building. When Burncoat is replaced, the suspect PCB containing materials will be removed and disposed of in accordance with applicable regulatory requirements.



#### **Conclusions and Recommendations**

In conclusion, it is our opinion that the BMPs are being implemented in an effective manner at Burncoat High School. We recommend that Facilities personnel recaulk the areas where sections of and/or entire seams of caulk appeared missing. Additionally, cleaning should be performed as needed where dust accumulation was identified as "moderate". We also recommend that the next quarterly (first quarter of the 2023-2024 School year) on-site visit be conducted in September of 2023.

Should you have questions or require additional information, please contact the undersigned.

Sincerely,

**Staff Scientist** 

O'Reilly, Talbot & Okun Associates, Inc.

Ionathan Hermanson, CHMM

Robert Kirchherr, CSP

Principal

**Attachments** Table 1 – Summary of Observations for Burncoat High School

cc Mr. Richard Ikonen, Facilities Director

Table 1 - Summary of BMP Observations
Burncoat High School
179 Burncoat Street
Worcester, MA 01602
June 28, 2023

Room	Condition of Caulk	Condition of Univents	Dust Accumulation	Comments
A-Hallway	VG	VG	L	
A-18	VG	VG	VG	
B-6	VG	VG	М	
B-2	VG	VG	L	
B-3	VG	VG	VG	
B-17	VG	VG	М	
B-16 Cafeteria	VG	VG	VG	
B-21	VG	VG	VG	
B-23	VG	VG	VG	
B-25	VG	VG	L	
C-Hallway	VG	VG	VG	3rd window from left, bottom pane, left and right seams missing caulk. 6th window from left, middle pane, bottom seam missing 2" of caulk.
C-3	VG	VG	М	
C-2	VG	VG	VG	
C-15 Library / Media Center	VG	VG	VG	
C-21	VG	VG	VG	
E-1	VG	VG	L	
E-5	VG	VG	VG	
E-5A	VG	VG	VG	
C to D Transition Hallway	VG	VG	VG	
D-5	VG	VG	M	
D-20	VG	VG	М	
F-2	VG	VG	VG	
F-6	VG	VG	L	
Gym Hallway	VG	VG	L	

# **CATEGORIZATION**

Very good = VG: disturbance or dust or debris minimal

Little = L: enough dust to leave a residue on a gloved finger or little disturbance

Moderate = M: visible accumulations of dust or moderate disturbance

Significant = S: thick layer of dust or significant distrubance