



September 22, 2017
File No. 5171-06-01

Mr. Joshua Watkins, Environmental Coordinator
Worcester Public Schools
20 Irving Street
Worcester, MA 01609, MA 02035

RE: August 2017 PCB BMP Quarterly Examinations
Burncoat High School

Dear Mr. Watkins,

At the request of the Worcester Public Schools, O'Reilly Talbot & Okun Associates, Inc. (OTO) has prepared this letter report to summarize our observations of materials in the subject school suspected of containing PCBs (polychlorinated biphenyls). This work is one part of the School Department's ongoing self-assessment of its best management practices (BMPs). The assessment was conducted in accordance with our June 30, 2017 proposal, and the Worcester Public Schools' BMP program.

The assessment consisted of: 1) the visual evaluations of the condition of caulk; 2) the condition of plenum air vents; and 3) the degree of dust present on windowsills and window frames at the school. OTO conducted these observations on Monday, August 21, 2017, in the presence of yourself and facility staff.

OTO observed 28 rooms in the Burncoat High School building, including the cafeteria, kitchen, library, faculty break rooms and offices, auto trade shop, and classrooms, with general observations of hallway areas. General observations are summarized in the enclosed Table 2, and selected representative photographs are attached.

The overall quality of BMPs was very good for most of Burncoat. The interior over-caulking was intact in the spaces observed except for minor pieces of material missing from rooms D6A, E4 and F2. The vents for the sub-floor heating plenum were free of significant dust and debris.

WPS staff indicated on September 19, 2017 that the missing over-caulk in rooms D6A, E4 and F2 had been restored, along with the library, where no original caulking was present, but where new caulk was applied to seal an air gap. Over-caulking was also applied to the H-wing, which is occupied by the music department. The music department is actually located in the Burncoat Middle School building.


Certain low-occupancy areas such as the auto trade shop room and the hallway outside the gymnasium exhibited minor accumulated dust. School maintenance staff indicated that windowsills and adjacent surfaces had been wet-wiped prior to the start of classes in accordance with School Committee policy.

Conclusions and Recommendations

In conclusion, our observations indicated that BMPs are being maintained to a high standard. OTO understands that WPS has requested these observations be conducted on a quarterly basis. We therefore suggest the next site visit be conducted in November 2017.

Should you have questions or require additional information, please contact the undersigned.

Very truly yours,
O'Reilly, Talbot & Okun Associates, Inc.



Thomas B. Speight, CHMM
Project Manager



James D. Okun, LSP
Principal

Attachments

Table 1 – Summary of Observations for Burncoat High School
Selected Photographs from Burncoat High School