



Worcester Public Schools

Worcester, Massachusetts



Facilities Management
Department

Dr. John E. Durkin Administration Building
20 Irving Street
Worcester, Massachusetts 01609-2493

Tel. (508) 799-3151
Fax (508) 799-3144
bedardj@worcesterschools.net

James Bedard
Facilities Director

September 29, 2020

Dear Staff, Parents and Students of the Worcester Public Schools:

In compliance with the U.S. Environmental Protection Agency (EPA) Asbestos Hazard Emergency Response Act (AHERA), in the fall of 1989, the Worcester Public Schools began inspections of each of our school buildings for asbestos-containing building materials. The inspection findings and asbestos management plans are on file in each school administrative office.

The EPA requires that re-inspections of the asbestos-containing materials be performed every 3 years. Accredited Asbestos Inspectors performed these re-inspections in October of 2019. An accredited Asbestos Management Planner reviewed the results of the re-inspection and recommended actions that the Worcester Public Schools should continue to implement to properly manage asbestos-containing materials in our buildings.

The original AHERA inspection reports, as well as results from the recent re-inspection, are on file in the management plan in the school's administrative office. Everyone is welcome to view this at any time during normal school hours (Monday through Friday). The Worcester Public Schools AHERA Coordinator, James Bedard, is available at (508) 799-3151 to answer any questions you may have about the procedures utilized to properly manage asbestos in our buildings.

Sincerely,

James Bedard
Worcester Public Schools
AHERA Coordinator