

X. GENERAL BUSINESS
Administration/Mr. O'Connell/
Mr. Foley/Ms. Colorio/
Mr. Monfredo/Miss Biancheria
(June 6, 2017)

CURRENT ITEM - gb #7-103.1
S.C. MEETING - 6-15-17

1ST ITEM gb #7-103 S.C.MTG. 4-6-17
2ND ITEM gb #7-103.1 S.C.MTG. 6-15-17

ITEM:

Response of the Administration to the request to address the varied defects and conditions affecting the wall separating the property of Tatnuck School from that occupied by the Tatnuck Square Center, 1097-1099 Pleasant Street, and the land in the vicinity of the wall, which include, and are not limited to:

- the deterioration of parking lot paving in the Center due to erosion from water flowing through the wall
- the location of the Tatnuck School dumpster adjacent to the land of the Center
- the exposed wires along the wall, and
- the deteriorating segments of the wall itself.

ORIGINAL ITEM: Mr. O'Connell/Mr. Foley/Ms. Colorio/Mr. Monfredo/
Miss Biancheria (March 10, 2017)

To address the varied defects and conditions affecting the wall separating the property of Tatnuck School from that occupied by the Tatnuck Square Center, 1097-1099 Pleasant Street, and the land in the vicinity of the wall, which include, and are not limited to:

- the deterioration of parking lot paving in the Center due to erosion from water flowing through the wall
- the location of the Tatnuck School dumpster adjacent to the land of the Center
- the exposed wires along the wall, and
- the deteriorating segments of the wall itself.

PRIOR ACTION:

4-6-17 - Referred to the Administration for a report back in June 2017.

BACKUP:

The repair and replacement of the retaining wall for Tatnuck Magnet School is included in the district's five year capital renovations & repair project budget list for the 2019-2020 fiscal year (as contained on page 170 of the FY18 budget book).

RECOMMENDATION OF MAKER:

RECOMMENDATION OF ADMINISTRATION:

Accept and file.